

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 12028
2. NAME OF OPERATOR Jerome P. McHugh		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1740' FNL - 800' FEL		8. FARM OR LEASE NAME Chaco Plant
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6030' GR	9. WELL NO. 3R
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT NIPP - Pictured Cliffs
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		11. SEC., T., S., M., OR BLM. AND SURVEY OR AREA Sec 20, T26N, R12W
		12. COUNTY OR PARISH San Juan
		13. STATE NM

NOTICE OF INTENTION TO: TEST WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREAT <input type="checkbox"/> SHOOT OR ACIDIZE <input type="checkbox"/> REPAIR WELL <input type="checkbox"/> (Other) <input type="checkbox"/>		PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETE <input type="checkbox"/> ABANDON* <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	SUBSEQUENT REPORT OF: WATER SHUT-OFF <input checked="" type="checkbox"/> FRACTURE TREATMENT <input type="checkbox"/> SHOOTING OR ACIDIZING <input type="checkbox"/> (Other) <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> ABANDONMENT* <input type="checkbox"/>
---	--	---	--	--

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

3-11-77
 Moved in and rigged up Morrow Drilling Company. Spudded 7-7/8" hole @ 1:00 PM 3-11-77. Drilled to 39'. Ran 1 jt 5-1/2" OD 14# ST&C csg. TE 38.60' set @ 39' GR cemented w/6 sx. Job complete 3:00 PM 3-11-77.

3-18-77
 TD 1260'. Ran 39 jts 2-7/8" OD 6.5# J-55 8R EUE tbg for csg. TE 1231.69' set @ 1231' GR. Cemented w/75 sx BJ 2% Lodense with 1/4# Cello-flake/sk. Recip pipe and had good mud returns while cementing. Max cementing press 500 psi. Bumped plug w/1800 psi, released to 700 psi. Shut-in. POB 3:00 PM 3-18-77.



APR 8 1977

18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan TITLE Petroleum Engineer DATE 4-7-77

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: