4-USGS (Farmington) 1-Southern Union (Sentz) 1-File

Form 9–331 Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 22046
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
• 11	Hard Deal
1. oil gas well other  2. NAME OF OPERATOR	9. WELL NO. 2R
Dugan Production Corp.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	WAW Fruitland PC
Box 208, Farmington, NM 84701	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SUBFACE: 1850' FNL - 1190' FEL	Sec. 18 T26N R12W
AT SURFACE: 1690 FINE - 1190 FEE AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5972 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ` \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
SHOOT OR ACIDIZE	-CEIVED
REPAIR WELL	(NOTE: Report resits of multiple completion or zone
PULL OR ALTER CASING	change on Form (-330.)
MULTIPLE COMPLETE	OCT 04 1979 (1-2) 1 2 2 2 3 3
	GEOLOGICAL SURVEY
(other) FA	RMINGTON, N. M.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	lirectionally drilled, give subsurface locations and nt to this work.)*
8-9-79 Foam fraced perfs 1126-34 and 1	141-46 w/70 quality foam by
Western Co. and Nowsco. Used 7	74 bbls wtr. 19 gals adatodu.
15,000# 10-20 sand and 97,040 s	of Of Nitrogen. Initial
treating pressure 2900 psi, Ave IR 4.5 B/M on fluid, 15 B/M ove	2. 2100 ps1, Mill 1300 ps1, Ave
stdg pressure 900 psi. Left we	sll shut in two hours. Opened
to atmosphere on 1/2" positive	choke. Checked well after 1
hour Unloading considerable a	amount of sand and spray of water.
Left open to atmosphere overnig	jht. Tagija jaginas ja
	TE 11101 0 11101 00
Landed tbg and nippled up wellh	R EUE tbg. TE 1112' set @ 1110' GR. nead. Left tbg open for 7 hrs. Shut in.
Subsurface Safety Valye: Manu. and Type	Set @Ft.
18. I hereby certify that the foregoing is true and correct	10-3-79
SIGNED THE President TITLE President	DATE
(This space for Federal or State of	fice use) - VOIL CON CONTRACTOR
APPROVED BY TITLE	DATE DIST
CONDITIONS OF APPROVAL, IF ANY:	