## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY			<b>6.</b> IF INDIA	AN, ALLOTTEE C		ΛE
				, ខ្នុត្តិ	<u> </u>	<u>-</u> -
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)			7. UNIT A	GREEMENT NAI	MES 5 E.	-
				7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		Ī
			•	R LEASE NAME	म उन्ह	٠
1. oil  gas			<b>-</b> ∤	EDERAL E	Ide of property	
1. oil gas well well	other DRY HO	NT.F	9. WELL N		<u> </u>	ر <del>ن</del> -
2. NAME OF OPERATOR			3	160 160 160	- 취 - 중급)	=
DOME PETROLEUM CORPORATION				R WILDCAT NA	ME	<u>-</u>
3. ADDRESS OF OPERATOR 501 Airport Drive			~~**	TLAND-PICT		្តិ ទីទ
Suite 107, Farmington, NM 87401						
		., R., M., OR BL	K. AND SURV	ET U		
<ol><li>LOCATION OF WELL (F below.)</li></ol>	' <b>!</b>			<u>ર</u>		
AT SURFACE: 1650' FSL, 990' FEL				T26N, R12		
AT TOP PROD. INTERVAL:			Į.	Y OR PARISH		<u>=</u>
AT TOTAL DEPTH:			SAN JUAN		JEW MEXICO	<u>ي</u>
16 OUEOK ADDDODDIATE	14. API NO.	Janua ay Ju July July July July	_ P _ 3 8 8 8	Ė.		
16. CHECK APPROPRIATE REPORT, OR OTHER	·			<u>-</u>		
REPORT, OR OTHER	15. ELEVAT	JONS (SHOM I				
REQUEST FOR APPROVAL	6150 GR	<u> </u>	<u> </u>	:		
TEST WATER SHUT-OFF		NT REPORT OF:		1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	ک نے کے کے اس کے اس اس کے اس	<u> </u>
FRACTURE TREAT	H H		-IVED	\4 # # # # # # # # # # # # # # # # # # #	edar bina Binyosi Binala Binala Binala	) 9
SHOOT OR ACIDIZE	H H	1 RFC	EIVED	\=\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		<u> </u>
REPAIR WELL	ā ñ		(NATEA Rep	ort results of mult	inle completion	Or zon
PULL OR ALTER CASING		CER	1 2 ME Rep char rocical Surve ncion. N. M.	nge on Form 9-33	(0.) = = = = = =	
MULTIPLE COMPLETE		L LL.U	1.0			= [
CHANGE ZONES		1	LOCICAL SURVE	* <b>\$</b> 8.55		
ABANDON*		U. S. CARMI	NCION. N. M.	<del></del>		ءَ ۽
(other)		11111		ម្រើ មិន មិន មិន មិន	- 본 토론의	<i>=</i>
measured and true ver	OR COMPLETED OPER te of starting any propo tical depths for all marke JUG AND ABANDON F	sed work. If well is ers and zones pertin	directionally dri ent to this work.	illed, give subsu	urface location	dates ns and E
PLUG NO.	INTERVAL	FEET S	SACKS CEMEN	17 년 10 년 17 년 12 년 18 년 17 년 18 년 18 년 18 년 17 년 18 년 18 년 18 년 18 년	th Than Tendeliosoft of the sea out spirit the sea out spirit to the sea out out on the sea out out out	Ē E
	40504 40004		50 1	Angar Ingu Anacar s Anacar s Angar antaph Anta Sitte TT		<u> </u>
1	1050'-1300'		50 sacks			î.
2	0'-200'	200 <b>'</b>	50 sacks	) 1944 91 6 1965 1976 1976		ĝ
_					- 8 1.3 <del>- 1</del>	5
Cut surface casing off 4' below ground level				KI115.EECI	lean 10ca	tion
and fence pit	•					<u>.</u>
						Ē
					Frank 1	Ĺ
				1	E Books 1	₹ ·
				TE E E E	<b>3€/30</b> 6 =	<u> </u>
Subsurface Safety Valve: Ma	anu. and Type			Set @	- MO1	$\perp$ $_{\rm F}$
-				13 mil 30	题 言言	ļ.
18. I hereby certify that the	foregoing is true and cor	rrect		- Jan 50		2
SIGNED SIGNED HOLLER	IGSWORTH TITLE	DRLG & PROD	FOREMABATE I	ebruary 8	1980 -	=
	(This spac	e for Federal or State o	office use)	48545	3 <u>4 7 </u> ;	=
					F	=
APPROVED BY CONDITIONS OF APPROVAL, I	TITI	LE	DATE		A 175	<u> </u>
				<b>APPR</b>	(3) A F	U
		MALOCOL		Line and		ت
MMOCOI  The See Instructions on Reverse Side				Bo, fr		
				MAR	~3 1 <del>980=</del>	
				James 7	Sent	
				JAMES	F. SIMS	<b>,</b>
				U SAME		

Budget Bureau No. 42-R1424

DISTRICT OIL & GAS SUPERVISOR

5. LEASE

NM 16473