L____



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No.	079521

Unit Sen Juan 26-5 Unit 14-06-001-949

SUNDRY NOTICES AND REPORTS ON WELLS

	TION TO DRILL		SUBSEQUENT REPORT OF WATER SI			-OFF	
NOTICE OF INTENT	TION TO CHANGE PLANS		SUBSEQUENT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING			
NOTICE OF INTENT	TION TO TEST WATER SHU	T-0FF	SUBSEQUENT	SUBSEQUENT REPORT OF ALTERING CASING			
NOTICE OF INTENT	TION TO RE-DRILL OR REP	REPAIR WELL SUBSEQUENT REPO			ORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENT	TION TO SHOOT OR ACIDIZ	CIDIZE SUBSEQUENT REP			ORT OF ABANDONMENT		
	TION TO PULL OR ALTER O		SUPPLEMENT	ARY WELL HIS	TORY		
NOTICE OF INTENT	TION TO ABANDON WELL.						
	(INDICATE ABOV	E BY CHECK MARK	NATURE OF REPOR	r, NOTICE, OR	OTHER DATA)	1 2
			•	-	Apr 1	1.7	, 19
⁷ ell No 3	is located	990 ft. from	S line and	1 990 f	t. from	line of	sec. 3
SW Sec.	Sec. No.)	201	5W	N.M.P.1			
			Range)	(Meridi			
Blanco (Field		Rio Ar	Subdivision)			or Territory)	0
ten 111 jo regular ce	Total Depth 3 inte 7 5/8", J-ment, 35 sacks	95, 26.40#, Posmix, 25	casing (3 Gel, 15 cm	600') sa	nt at 3	610' wit	h 35 se follow
Held 1000#	cks Neet coment for 30 minutes	3.				12.50	
	suc by compared	The box sel	ME SAM.				₹.
Top of cem							The !
						Bur of	On S
	t this plan of work must r	eceive approval in w	vriting by the Geol	ogical Survey	before op a	BR CO	on a consenced.
I understand that	t this plan of work must re			ogical Survey	before option	BR CO	commenced.
I understand that			1				
I understand that ompany	l Paso Natural	Gas Company	1	ogical Survey			