

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget ~~San Juan~~ No. 3358.4.  
Approval expires 12-31-60.

Land Office 078496  
Lease No. San Juan 26-7 Unit  
14-09-001-459  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 11

57


Well No. 72 (PM) is located 1650 ft. from XXX line and 1090 ft. from XXX line of sec. 19  
SW Section 35 200 N S.M.P.M. W 35  
White Bluffs (Twp. Rio Arriba) (Meridian) New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 3-23-57.  
On 3-25-57. Total Depth 175'.  
Ran 4 joints, 10-3/4", 32.75#, Armo S.W. casing (161')  
set at 171' with 250 sacks regular cement circulated to surface.  
Held 500' 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company  
Box 997  
Address Farmington, New Mexico

By W. F. Dyer  
Petroleum Engineer

Title \_\_\_\_\_