NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Return Gas Company Address Box 990, Farmington, New Mexico									
Lease San Juan 28-5 Unit			Well No.	Unit Letter	Section 35	Township 28-	N R	ange 5-W	
Date Work Po	5-1-61	o Mesa V	erde	County Rio Arriba					
THIS IS A REPORT OF: (Check appropriate block)									
Beginning Drilling Operations Casing Test and Cement Job Cher (Explain):									
Plugging Remedial Work					Water Fracture				
5-1-61 Total Depth 5929. C.O.T.D. 5844. Water fractured Mess Verde perforated intervals 5844-36;5832-26; 5816-04;5788-78;5764-56;5722-5714; with 76,800 gallons water and 55,000# sand. Breakdown pr 1800#, max pr 4000#, avg tr pr 2500#. Injection rate 13.3 BPM. Flush 3360 gallons. 4 stages, 60 balls dropped.									
Witnessed by Position Company									
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY									
D F Elev. T D PBTD Producing Interval Competition Date									
Dr Elev.			FBI	FBID			Producing Interval		
Tubing Diameter Tubing		Tubing Depth	Depth		Oil String Diameter		Oil Strik	TTIATO/	
Perforated Interval(s)					_			V5 1961	
Open Hole Interval					Producing Formation(s) Ols Com. Ols T. 3				
			RESUL	TS OF WORK	OVER				
_	Date of Oil		Production Gas Produc		· · · · · · · · · · · · · · · · · · ·	roduction	GOR	Gas Well Potential	
Test	Test	BPD		CFPD		PD	Cubic feet/Bbl		
Before Workover									
After Workover									
OIL CONSERVATION COMMISSION					I hereby certify that the information given above is true and complete to the best of my knowledge.				
Approved by Original Signed Emery C. Arnold					Name Original Signed R. G. MILLER				
Title Supervisor Dist. # 3					Position Petroleum Engineer				
Date MAY 5 1961					Company El Paso Hatural Gas Company				
	 								

```
STATE OF NE - EXICO
   OIL CORS RVATION COMMISSIO
       ALL C DISTRICT OFFICE
S.HIA FE
File
S.C.S.
TRANS-OFTER
PROMATION O PICE
```