

(SUBMIT IN TRIPLICATE)

UNITED STATES RTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget	Bureau	No.	42-R35	8.4
Approv	al expire	38 12 -	-31-60.	

Lease No. 07646-A

Unit Sen Juon 20-7 Unit

14-00-001-459

GEOLOGICAL SURVEY			4.	14-03-04-479				
	Town white the state of the same			F	CEI	VED		
		IOMICES A	ND DEDOR	_	-			
	SUNDRY N	OTICES A	ND REPOR	12 ON WE		1 33 0		
NOTICE OF I	NTENTION TO DRILL		SUBSEQUENT REPO	RT OF WATER SHUT-OFF		X 41.7		
	NTENTION TO CHANGE PLAN	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING						
NOTICE OF INTENTION TO TEST WATER SHUT-OFF			SUBSEQUENT REPORT OF ALTERING CASING					
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL			SUBSEQUENT REPORT OF ABANDONMENT					
								1
NOTICE OF I	INTENTION TO ABANDON WE							
	(INDICATE	ABOVE BY CHECK MARK	NATURE OF REPORT, NOT	ICE, OR OTHER DATA)				
				Jace :	<u></u> 24	1 9 %		
			4		M_1	., 1/		
Wall No	91(14) is located	1 636 ft from	N line and 19	ft. from E	line of sec.	34		
			• ,	•				
WMS/4 50		20H (Twp.)	(Vi Ka.	(Meridian)				
o. Blanc	C and Sec. No.) Xt. &	,			manufaction is			
lanco M.	(Field)	(County o	r Subdivision)	(State or	Territory)	-		
	•		dimedi.					
The elevat	tion of the derrick f	loor above sea lev	vel is con ft.					
			LS OF WORK					
(State names o	of and expected depths to o	bjective sands; show siz ing points, and all o	es, weights, and lengths ther important proposed	of proposed casings; ind work)	icate mudding jo	be, cement-		
-2 5- 5 5	T.D. 3110'. Ann 90 joints w/125 sacks re followed by 90 Held 1000; for	gular cemant, sacks regular	12) Bank ius					
	Top of cement	o, temperatur	e survey at 20	23'.				
	and that this plan of work :				ons may be comm	nenced.		
	Box 997							
Address	Farmington, Re	v Mexico	Ву	Original Sign	red D. C. J	ohns:on		
			Title	Fetroleum E	ngineer			
			1 1616					