Form 9-851 a (Feb. 1961)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa Fe	
Lesse No. 079370	<i></i>
Unit San Juni 26-4 U	ui
14-03-001-933	

SUNDRY NOTICES AND REPORTS ON WELLS

SONDKI NOTICES I	AND REI OR IS ON WELLS
NOTICE OF INTENTION TO DRILL.	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MAP	RK NATURE OF REPORT, NOTICE, OR OTHER DATA)
·	
	August 14 , 19 59
Well No. 24-26 is located 920 ft. from	m. $\{S\}$ line and 1675 ft. from $\{W\}$ line of sec. 26
() Sec. and Sec. No.) (Twp.)	
Blanco MV & Dak. Vildest Rio (Field) (County	y or Subdivision) State or Territory)
The elevation of the derrick floor above sea l	
	AILS OF WORK
(State names of and expected depths to objective sands; show a ing points, and all	iizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- l other important proposed work)
On August 7, 1959 Total Dopth 8752 Ran 9 joints 5 , J-55, 18f casing regular occurr, 25 sacks Formix 14	(379.96) set at 6370-6750 with 25 sacks
Held 1000#/30 minutes.	AND THE PROPERTY OF THE PROPER
Top of cement by temperature surve	RECEIVED AUG 1 8 1959 AUG 1 8 1959
	OIL CON. COM. OIL ST. 3 In writing by the Geological Survey before operations may be commenced.
I understand that this plan of work must receive approval i	in writing by the Geological Survey before operations may be commenced.
Company 11 Paso Maturel Gas Company	
Address Box 997	-
Farmington, New Mexico	By ORIGINAL SIGNED B.H. MEANS
	Title Petroleum Engineer

