

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R359.4.
Indian Agency Navajo Agency
Allottee _____
Lease No. Contract 281
Builder Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
MAY 1 1962

May 7, 1962
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO


Builder
Well No. 12-45 is located 2730 ft. from N line and 240 ft. from W line of sec. 23
SW 1/4 NW 1/4 Sec. 23 23N 14W R. 14. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Builder Mine Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 7:30 A.M. 4/30/62. Drilled 134'. Ran (6 Jts) 12 1/2" 9-5/8" N-40-325 cas. Set at 134'. Cased w/ 75 cas w/ 25 Cased. N. O. C. 12 hours. 950 P.S.I. Test/30 min.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Secony Mobil Oil Company, Inc.

Address P. O. Box 3971

Durango, Colorado

By P. M. Barry

Title Dist. Prod. Supt.

WELL 5 FILE 1 RUN 1