

APPROVED
Form 9-331a
(Feb. 1961)

JUN 25 1956

JERRY W. LONG
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Budget Bureau No. 42-R388.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 078497
Unit San Juan 28-7 Unit
14-08-001-499

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 56 is located 1650 ft. from S line and 1800 ft. from W line of sec. 29
29 Section 29 29N 7W 18N
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco No Action New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6181 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6-7-56. Total Depth 5109'.
 Run 158 joints 5 1/8", 15.5#, J-55 casing (5079') set at 5109' with 150
 sacks regular cement, 150 sacks Fomix, 2 1/2 Gal.
 Held 1000# for 30 minutes.
 Top of cement by temperature survey at 3080'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Harrington, New Mexico

By S. Schulerman

Title Petroleum Engineer