(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079050
Var. Bran 00 6 40

Unit San Juan 28-6 Unit 14-08-001-1051

NOTICE OF I	NTENTION TO DOUL	
	NTENTION TO CHANCE DI ANG	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
	NTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ALTERING CASING
	NTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
	NTENTION TO PULL OR ALTER CASING.	SUBSEQUENT REPORT OF ABANDONMENT
	NTENTION TO ABANDON WELL	SUPPLEMENTARY WELL HISTORY
	ALENTION TO ABANDON WELL	With the column of the column
	(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)
		Ney 7 1957
SW Se	ection 29 201 6	$ \begin{cases} N \\ S \end{cases} \text{ line and } 1745 \text{ ft. from } \begin{cases} E \\ W \end{cases} \text{ line of sec. } 25 $ $ N \\ Range) \qquad (Meridian) $
Blanc		Tibe Hew Mexico Subdivision) (State or Tarritory)
	(county of	(State or Territory)
The elevation	on of the derrick floor above sea leve	el is <u>6513</u> ft.
	DETAII	S OF WORK
(State names of	and expected depths to objective sands; show sizes	s, weights, and lengths of proposed casings; indicate mudding jobs, cement her important proposed work)
	<u> </u>	important proposed work)
Unit	unit no. or-29. Inte well in	by Facific Northwest as the San Juan s within the limits of the San Juan 28-6 is Company will be the operator with name San Juan 28-6 Unit No. 51.
		riting by the Geological Survey before digrations may be commenced.
ompany	al Paso Matural G.s Compa	my
	71 ·	
Address	BOX 991	
Address	Farmington, New Mexico	By Original Signed D. C. Johns'o
ddress		By Original Signed D. C. Johns'o Title Petroleum Engineer

