

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office SP  
Lease No. 078496  
Unit San Juan 20-1  
14-26-001-400

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20, 1957

Well No. 75 (1M) is located 100 ft. from [N] line and 1000 ft. from [E] line of sec. 20

NE Sec. 20 20N 10W RM14  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wilacat & Blanco Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6070 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8-20-57 Total Depth 5062'.  
Ran 55 joints 5 1/2", 15.00, J-55 Liner (2260') From 2751' to 5055' with 150 sacks regular cement, 150 sacks foamix, 45 Gel, 1/64 Floccle/sk.  
Held 1000g for 30 minutes

Top of cement by temperature survey at 2751'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 501  
Farmington, New Mexico

By Original Signed D. C. Johnston  
Title Petroleum Engineer