

(SUBMIT IN TRIPLICATE)

Indian Agency Jicarilla

Apache

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee -

Lease No. Contract No. 241

X	14	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lease: Boulder-Apache #1

July 24, 1961

Well No. 12-14 is located 1750 ft. from N line and 950 ft. from W line of sec. 61

<u>NW/4 Sec. 14</u> (1/4 Sec. and Sec. No.)	<u>28N</u> (Twp.)	<u>1W</u> (Range)	<u>New Mexico</u> (Meridian)
<u>Indesignated Gallup</u> (Field)	<u>Rio Arriba</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)	

The elevation of the derrick floor above sea level is 7360 ft. (est.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 9:30 pm on 7/20/61.
Drld. 13-3/4" hole to 139'.
Cmtd 4 joints of 10-3/4" csg @ 139' w/90 sx + 2% CaCl2. PD @ 8:30 am, 7/21/61.
After standing for 17 hours, pressure tested w/600 psi for 30 min; ok.
Drig. ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Socony Mobil Oil Company, Inc.

Address P. O. Box 3371

Durango, Colorado

By P. M. Barry
Title Dist. Prod. Supt.

cc: USGS (5)
GWR (1)
Dgo (1)