Form 9-881 a (Feb. 1961)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe	
Lease No.	020505 -B	

Unit San Juan 28-5 Unit 14-08-001-949

SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT OF WATER SHUT-OFF	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF ALTERING CASING	
SURSPOUENT REPORT OF RE-DRILLING OR REPAIR	
SUBSEQUENT REPORT OF ABANDONMENT	
SUPPLEMENTARY WELL HISTORY	
0il Frac.	χ.
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING

(INDI	CATE ABOVE BY CHECK	K MARK NATURE OF REPO	ORT, NOTICE, OR OTHER DA	TA)
				December 7 , 19 59
Well No. 35 (MD) is loc	ated 990 ft.	from S line an	nd <u>290</u> ft. from	W line of sec. 1. 2
SW/4 Sec. 19	25N (Twp.)	5/ii (Range)	M.M.P.M.	
Blanco M.V. & Wilder (Field)	t Dakota	Rio Arribe	New (St.	Mex 10FC 1 0 1959
The elevation of the derri	k floor above s	ea level is 6570	2. ft.	DIST. 3
	D	ETAILS OF WO	RK	
(State names of and expected depths		how sizes, weights, and k		s; indicate mudding jobs, coment-
max. pr. 3800, avg. 12-2-59 Total Depti Dakota perf. int. 7 sand. EDP 1500, max galbas. 12-4-59 Total Depti	tr. pr. 379 17955'. Tem 102-7710; 771 1. pr. 3700# 17955'. Tem 17618-7626	00#. I.R. 28 E porary bridge 16-7722 (2 DJ/ , avg. tr. pr. morary bridge (2 DJ/ft.) v/	Plug at 7740'. Plug at 7740'. Pt.) w/24,000; 3600#. I.R. 3	Oil fractured Upper gallons oil & 20,000# 5.3 BPM. Flush 12,180 . Oil fractured Grans oil & 20,000# sand.
I understand that this plan of we El Paso Natus Company			sological Survey before op	erations may be commenced.
Address Box 997				

Farmington, New Mexico

By ORIGINAL SIGNED B.H. MEANS

Title Petroleum Engineer