


1-211a (SUBMIT IN TRIPPLICATE)

Land Office Santa Fe  
Lease No. 079193  
Unit 23  
14-01-01-1051

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 1-211a is located 150 ft. from <sup>(N)</sup>/<sub>(S)</sub> line and 150 ft. from <sup>(E)</sup>/<sub>(W)</sub> line of sec. 22  
 22 22 (1/4 Sec. and Sec. No.) 22 (Twp.) 22 (Range) 22 (Meridian)  
 22 (Field) 22 (County or Subdivision) 22 (State Territory)

The elevation of the derrick floor above sea level is 4574 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill to 3370' and run 3 1/2" of 7 5/8" of 24' 3-51 Red Sea Casing  
 w/ Harris valve above and float collar at 3370' w/ 150 lb. and  
 70 lb. cement at 3370' a.s. 3-4-51 - casing test okay - 3-4-51



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Oil and Gas Development Company  
 Address 4131 East Main  
Farmington, New Mexico  
 By Original signed by T. A. Pagan  
 Title District Engineer

