



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 979290-A
Unit San Juan 26-7 Unit
14-08-001-459

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 15, 1956

Well No. 50 is located 990 ft. from N line and 950 ft. from E line of sec. 23
NE Section 23 28N 7W 14R
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco Rio Arriba New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5924 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

6-11-56. Total Depth 5020'.
 Run 184 joints 5 1/2", 15.20 lb, J-55 casing, (5017') set at 5020' with 150 sacks
 regular cement 150 sacks Pozmix, 2 1/2 gal, 1/8" Floccule/sk.
 Held 1000' for 30 minutes.
 Top of cement by temperature survey at 4230'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Zi Paso Natural Gas Co.

Address Box 997

Pecos, N.M.

By [Signature]

Title Petroleum Engineer

مجلسه اول در تاریخ ۱۳۰۲/۱۰/۱۵