Form	9-331 a
(Feb.	1951)

j	İ	
!	į	į
j	ļ	
ł	ļ	Ì
ļ		
ii		

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No.	42-R358.4.
Form Approved.	

Land Office Santa Fe

Lease No. 079289

Unit SET Sec. 14

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
	CURSO
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	A CIDITALE
MOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ALTERING CASING TO THE TOTAL TOTA
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO ABANDON WELL	SUPPLEMENTARY WELL HISTORY
(INDICATE ABOVE BY CHECK AND	
	NATURE OF REPORT, NOTICE, OR OTHER DATA)
San Juan Unit 28-7	July 1, 19 63
Well No. 136 is located and for the	6N1
or tt. from	S line and 1650 ft. from $\{E\}$ line of sec. 14
T20Nwn) K7W	
Wildcat Rio (count)	(Mertital)
(Field) Alo (County of	Subdivision)
The elevation of the 1 1 1 4	(State of Territory)
The elevation of the planting floor phoys for layer	/if -6490 ft. G.L.
DETAIL	C OF WORL
cotate names of and expected depths to objective sands; show sizes,	Waights and I
Ing points, and all all	
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with pof 1% HR7. Followed with 100 sacks Class ceturns. Cement bond log indicates	g to T.D. of 8694'. Ran 28 joints of 5-1/2" 15.5# J-55 (7052') casing landed @ 7889'.
Drilled 7-7/8" hole below 8-5/8" casin 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'.
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with portion of 1% HR7. Followed with 100 sacks Class "cturns. Cement bond log indicates	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'.
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with of 1% HR7. Followed with 100 sacks Classurus. Cement bond log indicates cement waiting on completion rig.	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'. 16% Gel, 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'.
Orilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with of 1% HR7. Followed with 100 sacks Classurus. Cement bond log indicates cement waiting on completion rig.	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'. 16% Gel, 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'.
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Commented with 65 sacks Class "C" with of 1% HR7. Followed with 100 sacks Class caturns. Comment bond log indicates can low waiting on completion rig. I understand that this plan of work must receive approval in writing on completion rig.	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'. 16% Gel, 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'.
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Commented with 65 sacks Class "C" with of 1% HR7. Followed with 100 sacks Classurus. Comment bond log indicates common waiting on completion rig. I understand that this plan of work must receive approval in writing the same of	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'. 16% Gel, 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'.
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with pf 1% HR7. Followed with 100 sacks Class cannot be completed and cates cannot be completed and cates cannot be completed as a complete complete cannot be completed as a complete cannot be completed as a complete complete cannot be completed as a complete complete cannot be completed as a complete co	g to T.D. of 8694'. Ran 28 joints of 5-1/2" " 15.5# J-55 (7052') casing landed @ 7889'. 16% Gel, 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'.
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with pf 1% HR7. Followed with 100 sacks Class cannot be completed and cates cannot be completed and cates cannot be completed as a complete complete cannot be completed as a complete cannot be completed as a complete complete cannot be completed as a complete complete cannot be completed as a complete co	ing by the Geological Suggest before T.D. of 8694'. Ran 28 joints of 5-1/2" 15.5# J-55 (7052') casing landed @ 7889'. 16% Gel, 6-1/4# Gilsonite per sack and .4 REFINED REFINED 1963 1963
Drilled 7-7/8" hole below 8-5/8" casing 15.5% J-55 (882') and 215 joints 5-1/2 Commented with 65 sacks Class "C" with portion of 1% HR7. Followed with 100 sacks Class caturns. Comment bond log indicates can low waiting on completion rig. I understand that this plan of work must receive approval in writing the properties of the proper	ing by the Geological Survey before operations may be completed. "15.5# J-55 (7052*) casing landed @ 7889*. 16% Gel. 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full Ment top @ 7170*. ONL DIST.
Drilled 7-7/8" hole below 8-5/8" casing 15.5% J-55 (882') and 215 joints 5-1/2 Commented with 65 sacks Class "C" with point of 1% HR7. Followed with 100 sacks Class caturns. Comment bond log indicates can low waiting on completion rig. I understand that this plan of work must receive approval in writing parameters of the properties o	og to T.D. of 8694'. Ran 28 joints of 5-1/2" "15.5# J-55 (7052') casing landed @ 7889'. 16% Gel. 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'. Original signed by
Orilled 7-7/8" hole below 8-5/8" casing 15.5% J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with of 1% HR7. Followed with 100 sacks Class caurns. Cement bond log indicates caused with a completion of completion rig. I understand that this plan of work must receive approval in writing parameters of the completion of the company — Delhi-Taylor Oil Corporation of the completion rig.	ing by the Geological Survey before operations may be companied. "15.5# J-55 (7052*) casing landed @ 7889*. 16% Gel. 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full Ment top @ 7170*. ON 1963 ON 1967
Drilled 7-7/8" hole below 8-5/8" casing 15.5# J-55 (882') and 215 joints 5-1/2 Cemented with 65 sacks Class "C" with per 1% HR7. Followed with 100 sacks Class ceturns. Cement bond log indicates certainly waiting on completion rig.	og to T.D. of 8694'. Ran 28 joints of 5-1/2" "15.5# J-55 (7052') casing landed @ 7889'. 16% Gel. 6-1/4# Gilsonite per sack and .4 ass "C" with 3/4 of 1% Halad 9 with full ment top @ 7170'. Original signed by