

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other \_\_\_\_\_
2. NAME OF OPERATOR  
El Paso Natural Gas Company
3. ADDRESS OF OPERATOR  
Box 289, Farmington, New Mexico 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1840'N, 1045'W  
AT TOP PROD. INTERVAL: 0  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other)	<input type="checkbox"/>

## SUBSEQUENT REPORT OF:

[illegible]

RECEIVED (NO)

MAY 21 1990

U. S. GEOLOGICAL SURVEY  
WASHINGTON, D. C.

Report results of multiple completion or zone change on Form 9-330.)

- |  |                         |
|--|-------------------------|
| 5. LEASE<br>SF 078497-A  |                         |
| 6. IF INDIAN, ALLOTTEE OR TRIBE NAME   |                         |
| 7. UNIT AGREEMENT NAME<br>San Juan 28-7 Unit   |                         |
| 8. FARM OR LEASE NAME<br>San Juan 28-7 Unit  |                         |
| 9. WELL NO.<br>30A (PM)  |                         |
| 10. FIELD OR WILDCAT NAME<br>Blanco PC & Blanco MV                                     |                         |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR<br>AREA Sec. 18, T-28-N, R-7-W<br>N.M.P.M. |                         |
| 12. COUNTY OR PARISH<br>Rio Arriba   | 13. STATE<br>New Mexico |
| 14. API NO.  |                         |
| 15. ELEVATIONS (SHOW DF, KDB, AND WD)<br>6854' GL                                      |                         |

- 5-9-80: TD 3827'. Ran 88 joints 7", 20#, K-55 intermediate casing 3816' set at 3827' Cemented w/314 cu. ft. cement. WOC 12 hours;held 1200#/30 minutes. Top of cement 2700'.
- 5-11-80: TD 6139'. Ran 61 joints 4 1/2", 10.5#, K-55 casing liner 2468' set 3672-6139' Float collar set at 6121'. Cemented w/ 428 cu. ft. cement. WOC 18 hours.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Ft. \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED N. G. Busco TITLE Drilling Clerk DATE May 16, 1980

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

ACCEPTED FOR RECORD

MAY 22 1980

FARMINGTON DISTRICT

FARMINGTON DISTRICT  
BY M. L. Kuchera

**\*See Instructions on Reverse Side**

**MACC**