



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Farmington, N.M.  
Lease No. 50592-95  
Unit Jicarilla Cont. #2h

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	<input checked="" type="checkbox"/> SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 14, 1956

Well No. 1 is located 330 ft. from N line and 300 ft. from E line of sec. 6

SE 1/4 Sec. 6 T28N R2W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

South Dulce Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per our telephone conversation of 3-13-56, we propose to abandon South Dulce No. 1 (refer your letter of Dec. 9-1955 - Jicarilla Contract #2h). Present condition - 13 3/8" casing at 831' w/550 sacks, 9 5/8" casing at 8412' w/800 sacks, two stage collars at 4005' with 300 sacks. All perforations in 9 5/8" casing are squeezed. Because of the two stage collars at 4005' w/300 sacks it seems inadvisable to set and pull 9 5/8" casing as you mentioned. We will cut well head off, place surface plug with regulation marker, clean location (fill and level) and permanently abandon well.

The proposed work will commence as soon as weather conditions permit.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address 816 Patterson Bldg.

Denver, Colorado

By \_\_\_\_\_

Title District Superintendent