



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan
Lease No. 1125
Unit San Juan 2-1-2 Unit
10-0-001-70

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 11 is located 400 ft. from N line and 100 ft. from E line of sec. 1
11-00-1 (1/4 Sec. and Sec. No.) 20N (Twp.) 10E (Range) 10W (Meridian)
11-00-1 (Field) Elko Arriba (County or Subdivider) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 10,000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 1-30-50. Total depth 170'.
Run 4 joints, 10 3/4", 32.0 lb, Arma S. S. casing (111') set at 170' with 100
sacks regular cement, 3% CaCl circulated to surface.
Run 100, 5 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company
Address 1001 1st
Albuquerque, New Mexico
By Original Signed D. C. Johnston
Title Retroleum Engineer