DEC 2 9 1997

Meter Number:71183 Location Name:SAN JUAN 28-7 UNIT #20

Location:TN-28 RG-07 SC-08 UL-E

2 - Federal

NMOCD Zone:OUTSIDE

Hazard Ranking Score:00

RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1.000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

10⁻⁹ to 10⁻¹³ cm/sec Sandstone 10⁻¹² to 10⁻¹⁶ cm/sec Shale 10⁻¹² to 10⁻¹⁵ cm/sec Clav

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 1183 Location: San Juan 28-7 Unit 20 Operator #: D2D3 Operator Name: Amoco P/L District: Blanco Coordinates: Letter: E Section 8 Township: 28 Range: 7 Or Latitude Longitude Pit Type: Dehydrator Location Drip: Line Drip: Other: Site Assessment Date: 6/8/44 Area: 13 Run: 7/
	NMOCD Zone: (From NMOCD Maps) Inside Outside Depth to Groundwater Less Than 50 Feet (20 points) The points of the points
SITE ASSESSMENT	Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? (1) YES (20 points) (2) NO (0 points)
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points)
	(Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only) (2) > 100'
70	TOTAL HAZARD RANKING SCORE: POINTS
REMARKS	Remarks: Relline-Outside, Vuln - Outside 3pits. Closel. Pit Dry
REN	
	Prich TA

ORIGINAL PIT LOCATION Original Pit: a) Degrees from North 46 Footage from Wellhead 59 b) Length: 45 Width: 33 Depth: 3 ORIGINAL PIT LOCATION Remarks: Pictures@1429 (1-4) roll7 Dunp Truck Bermed + Fenced area of pit is 45 x33', Actual pit area is 33'x30'x3' REMARKS Completed By: Date

FIELU PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 7/183 Location: SAN Juan 28-7#20 Coordinates: Letter: E Section 8 Township: 28 Range: 7 Or Latitude Longitude Date Started: 8-23-94 Run: 13 7/
FIELD OBSERVATIONS	Sample Number(s): MK 233 Sample Depth: 3' Feet Final PID Reading 202 PID Reading Depth 3' Feet Yes No Groundwater Encountered \(\begin{array}{c c} \omega & \ome
CLOSURE	Envirotech L Tierro
	Other Facility Name:
REMARKS	Remarks: EPNG lines narked Soil Gray Slight Hydrocaryon
	Signature of Specialist: Morgo Xillian (SP3191) 03/16/94



FIELD SERVICES LABORATORY

ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

	5 0	1 Lab ID 94 6000		Field II	
	0 0	N/A			_
				MK 283	SAMPLE NUMBER:
			71183 N/A		MTR CODE SITE NAME:
	į	1147	8.23.94		SAMPLE DATE TIME (Hrs):
]		N/A			SAMPLED BY:
1	14	8-25-94 9/75/14		DATE OF TPH EXT. ANAL.:	
1	,	۵/۵ مارم		DATE OF BTEX EXT. ANAL.:	
]	Brown/grey teresand			16	TYPE DESCRIPTION:
					REMARKS:
			ESULTS	R	
	QUALIFIERS		UNITS	RESULT	PARAMETER
V(ml)	M(g)	DF Q			
28	023		MG/KG	41,800	TPH (418.1)
			PPM	202	HEADSPACE PID
			%	90.9	PERCENT SOLIDS
		18.1	TPH is by EPA Method 4		
					F = Dilution Factor Used
	<u>023</u>	.18.1	PPM %	202 90,9	



