

District I

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer, Artesia, NM 88211

District III

1000 Rio Brazos Rd. Aztec, NM 87410

State Of New Mexico

Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND 1 COPY TO

SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORTOperator: Conoco Inc.Telephone: 505-324-5837Address: 3315 Bloomfield Hwy - Farmington, NM 87401Facility Or: San Juan 28-7 #21

Well Name

Location: Unit or Qtr/Qtr Sec

Unit N

Sec

9 T

28N R

7W County

Rio Arriba

Pit Type: Separator

Dehydrator

Other

TDP

Land Type: BLM X State

Fee

Other

Pit Location:
(Attach diagram)

Pit dimension:

length

8'width 6' depth4'

Reference:

wellhead

X

other

Footage from reference:

50

Direction from reference:

40

Degrees

X

East

of

X North

West

South

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet

(20 points)

50 feet to 99 feet

(10 points)

Greater than 100 feet

(0 points)

Total

0

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)

No (0 points)

Total

0

Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet

(20 points)

(20 points)

200 feet to 1000 feet

(10 points)

(10 points)

Greater than 1000 feet

(0 points)


(0 points)

Total

0

RANKING SCORE (TOTAL POINTS):

0

Date Remediation Started:		No Remediation Necessary		Date Completed:		N/A	
Remediation Method:		Excavation:		Approx. cubic yards			
(Check all appropriate sections)		Landfarm		Insitu Bioremediation			
		Other					
Remediation Location:		Onsite		Offsite			
(ie. landfarmed onsite, name and location of offsite facility)							
General Description Of Remedial Action:							
Ground Water Encountered:		No		X		Yes	
				Depth			
Final Pit:		Sample location		Center of Pit Bottom			
Closure Sampling:							
(if multiple samples attach sample results and diagram of sample locations and depths)		Sample depth		3'			
		Sample date		11/1/2001		Sample time	
						12:00 PM	
		Sample Results					
		Benzene (ppm)		2.44			
		Total BTEX (ppm)		13.84			
		Field headspace (ppm)		N/A			
		TPH		401			
Ground Water Sample:		Yes		No		X	
						(If yes, attach sample results)	
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF							
DATE		5/2/2002		PRINTED NAME		John E. Cofer	
SIGNATURE				AND TITLE		Environmental Coordinator	

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Conoco	Project #:	97070-003-416
Sample ID:	Water Dump Pit	Date Reported:	11-06-01
Laboratory Number:	21417	Date Sampled:	11-01-01
Chain of Custody:	9636	Date Received:	11-02-01
Sample Matrix:	Soil	Date Analyzed:	11-06-01
Preservative:	Cool	Date Extracted:	11-05-01
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	2,440	1.8
Toluene	3,640	1.7
Ethylbenzene	1,340	1.5
p,m-Xylene	4,350	2.2
o-Xylene	2,070	1.0
Total BTEX	13,840	


ND - Parameter not detected at the stated detection limit.


Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	98 %
	1,4-difluorobenzene	98 %
	Bromochlorobenzene	98 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: San Juan 28 - 7 #21.


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco	Project #:	97070-003-416
Sample ID:	Water Dump Pit	Date Reported:	11-07-01
Laboratory Number:	21417	Date Sampled:	11-01-01
Chain of Custody No:	9636	Date Received:	11-02-01
Sample Matrix:	Soil	Date Extracted:	11-05-01
Preservative:	Cool	Date Analyzed:	11-06-01
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	397	0.2
Diesel Range (C10 - C28)	4.4	0.1
Total Petroleum Hydrocarbons	401	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **San Juan 28-7 #21.**



Analyst


Review

09636

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615



Lease Name: S.J. 28-7 #21

Federal/ Indian Lease No: SF-087497-A

CA No.: _____

Unit : N

Legal Description: Sec. 9 T 28 N R 7 W

County: Rio Arriba

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM