

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-11121

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME San Juan 28-6 Unit
2. NAME OF OPERATOR El Paso Natural Gas Company	8. FARM OR LEASE NAME San Juan 28-6 Unit
3. ADDRESS OF OPERATOR PO Box 990, Farmington, NM 87401	9. WELL NO. 123 (P&A)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 800'N, 800'E	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 16, T-28-N, R-6-W NMPM
15. ELEVATIONS (Show whether PF, RT, GS, etc.) 6738'GL	12. COUNTY OR PARISH Rio Arriba
	13. STATE NM

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated and true vertical depths for proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for proposed work.)

The subject well has been plugged and abandoned in the following manner

- 8-15-73 Ran cement retainer set at 2670'.
- 8-16-73 Squeezed below cement retainer with 150 sks. of cement.
- 8-17-73 Found free point of 4 1/2" production casing at 379'. Attempted to shoot off casing. Casing would not come free.
- 8-18-73 Spotted a 30 sk. cement plug at 379'. Squeezed 25 sks. out hole left after attempting to shoot off casing.
Installed a Plug and Abandonment marker with 15 sks. of cement at the surface.

Note: location will be cleaned and leveled at a later date at which time an additional sundry notice will be filed.

18. I hereby certify that the foregoing is true and correct

SIGNED CH. Jones TITLE Petroleum Engineer DATE October 19, 1973

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE

OCT 24 1973

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY

