UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wel	ls
1. Type of Well GAS	5. Lease Number SF-079519A 6. If Indian, All. or Tribe Name
2. Name of Operator	7. Unit Agreement Name
MERIDIAN OIL 3. Address & Phone No. of Operator	San Juan 28-5 Unit 8. Well Name & Number San Juan 28-5 U #82
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1031'FSL, 1150'FWL Sec.22, T-28-N, R-5-W, NMPM	10. Field and Pool Basin Dakota 11. County and State Rio Arriba Co, NM
1.2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE Type of Submission Type of Act	, REPORT, OTHER DATA
x Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Casing Repair	Change of Plans _ New Construction _ Non-Routine Fracturing _ Water Shut off Conversion to Injectio
1.3. Describe Proposed or Completed Operations The subject well is currently listed as inactivite. The well has not produced due facilities. The well, however, is capable of production. The surface will be returned to production within 365 days.	to lack of orinadequate surface ce facilities will be restored and the we
COLUMBIA FEBRUSSA COLUMBIA	0 - 7
THIS EMPHOYEL EXPINED FEB 0 1-1	995
14. I hereby certify that the foregoing is true and co	orrect.
Signed State State (KS) Title Regulatory Aft	<u> </u>
(This space for Federal or State Office use) APPROVED BY Title CONDITION OF APPROVAL, if any:	APPRO VED
ي ب	FEB 09 1994

MACCO