| Form | 9-331 |
|------|-------|
| (May | 1963) |

UNITED STATES

SUBMIT IN TRIPLICATE.

| DEPARTMENT OF THE INTERIOR (Other Instructions on Interior of the Interior of | | | 5. LEA | 5. LEASE DESIGNATION AND SERIAL NO. | | | | |
|---|---|--|--------------------------------|-------------------------------------|---|------------------------|--|--|
| GEOLOGICAL SURVEY | | | | | SF 079050-B | | | |
| (Do not | | OTICES AND REPORTS oposals to drill or to deepen or plucification FOR PERMIT—" for suc | | 6. IF | | EE OR TRIBE NAME | | |
| OIL WELL | GAS X OTHE | R | | | it Juan 28-0 | | | |
| 2. NAME OF OPERATOR | | | | 8. FAR | 8. FARM OR LEASE NAME | | | |
| El Paso Natural Gas Company 3. ADDRESS OF OPERATOR | | | | San Juan 28-6 Unit | | | | |
| PO Box 990, Farmington, NM 87401 | | | 162 | 162 | | | | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* | | | | 10. FIELD AND POOL, OR WILDCAT | | | | |
| See also space 17 below.) At surface 800'S, 1650'W | | | | So. | So. Blanco P. C. Ext. | | | |
| 500 b, 1000 H | | | | | 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA | | | |
| | | | | 1 | | 8-N, R-6-W | | |
| | | | | 1 | PM | 5 11 , 1 1 5 17 | | |
| 14. PERMIT NO. | | 15. ELEVATIONS (Show whether | r DF, RT, GR, etc.) | | OUNTY OR PARIS | SH 13. STATE | | |
| | | 6604'GL | · | Rio | Arriba | New Mexico | | |
| 16. | Check | Appropriate Box To Indicate | e Nature of Notice, Report, or | Other D | ata | | | |
| NOTICE OF INTENTION TO: | | | QUENT RE | UENT REPORT OF: | | | | |
| TEST WATER | SEUT-OFF | PULL OR ALTER CASING | WATER SHUT-OFF | x | REPAIRING | WELL | | |
| FRACTURE T | | MULTIPLE COMPLETE | FRACTURE TREATMENT | | ALTERING | CASING | | |
| SHOOT OR A | | ABANDON* | SHOOTING OR ACIDIZING | _ | ABANDONM | ENT* | | |
| REPAIR WEL | L | CHANGE PLANS | (Other) | | | | | |
| (Other) | (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) | | | | | n on Well 'orm.) | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

5-3-72

Spud well. Drilled surface hole. Ran 4 joints 8 5/8", 24#, KS surface casing, 121' set at 133'. Cemented with 107 cu.ft. cement. Circulated

to surface. WOC 12 hours, held 600#/30 minutes.



U. S. GEOLOGICAL SURVEY DURANGO, COLO.

| 8. I hereby certify that the foregoing is true and correct | TITLE | Petroleum Engineer | DATE _ | May 4, 1972 |
|--|---------|--------------------|--------|-------------|
| (This space for Federal or State office use) | | | | |
| APPROVED BYCONDITIONS OF APPROVAL, IF ANY: | TITLE _ | | DATE _ | |