

District I
P.O. Box 1980, Hobbs, NM

District II
P.O. Drawer 00, Artesia, NM 88211

District III
1000 Rio Grande Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: CONDOL INC. Telephone: 505-324-5813

Address: 3315 Bloomfield HWY FARMINGTON N.M. 87401

Facility Or: SAN JUAN 28-7 # 161
Well Name

Location: Unit or qtr/qtr sec G sec 16 T 28N R 07W County SAN JUAN

Pit Type: separator ☐ Dehydrator ☐ other Blow Down Pit.

Land Type: BLM ☒, State ☐, Fee ☐, other ☐


Pit Location: Pit dimensions: length 4', width 4', depth 2'
(Attach diagram)

Reference: wellhead ☒, other ☐

Footage from reference: 65'

Direction from reference: 210 Degrees ☐ East ☐ North ☐
☒ West ☒ South

Depth To Ground Water:
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)



Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 points) 0

Wellhead Protection Area:
(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: 9-28-99 Date Completed: 9-30-99

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: onsite _____ offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description Of Remedial Action: Sample taker, Till Bottom of Pit 1'
IN - BACK Fill clean soil

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit:

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample location CENTER OF Pit.

Sample depth 5'

Sample date 9-22-99 Sample time 1522

Sample Results

Benzene (ppm) _____

Total BTEX (ppm) _____

Field headspace (ppm) 17

TPH 49.8

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEF

DATE 12-1-99

SIGNATURE

PRINTED NAME
AND TITLE

Judson Valdez P.L.

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco	Project #:	707003-105
Sample ID:	BDP - Grab	Date Reported:	09-29-99
Laboratory Number:	G109	Date Sampled:	09-22-99
Chain of Custody No:	7137	Date Received:	09-23-99
Sample Matrix:	Soil	Date Extracted:	09-27-99
Preservative:	Cool	Date Analyzed:	09-28-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	0.8	0.2
Diesel Range (C10 - C28)	49.0	0.1
Total Petroleum Hydrocarbons	49.8	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: San Juan 28 - 7 #161 OVM Reading 17.


Analyst


Review


7137

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615

Lease Name: San Juan 28-7 #161 Operator: SM Date: 9-22-99

Site Security
(Indicate North)



Lease Name: San Juan 28-7 #161
Federal/ Indian Lease No: NM SF 078497
CA No.:
Unit : G
Legal Description: Sect: 16 TP: 27N R: 7W
County: Rio Arriba, NM

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM