



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

August 23, 2001

Dolores Silseth
Burlington Res O&G Co
PO Box 4289
Farmington NM 87499

Re: San Juan 28-5 Unit #93, G, 15-28N-05W API 30-039-20876

Dear Ms. Silseth:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before December 1, 2001.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: Well file
CP