

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED | 3 |
| DISTRIBUTION           |   |
| SANTA FE               | 1 |
| FILE                   | 1 |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               | 1 |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|                                |   |
|--------------------------------|---|
| 5a. Indicate Type of Lease     |   |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |   |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |   |
|--|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>   |  | 7. Unit Agreement Name                                  |
| 2. Name of Operator<br>El Paso Natural Gas Company   |  | 8. Farm or Lease Name<br>San Juan 28-7 Unit             |
| 3. Address of Operator<br>P. O. Box 990, Farmington, NM 87401  |  | 9. Well No. <u>224</u><br><del>San Juan 28-7 Unit</del> |
| 4. Location of Well<br>UNIT LETTER <u>H</u> , <u>1450</u> FEET FROM THE <u>N</u> LINE AND <u>800</u> FEET FROM<br>THE <u>E</u> LINE, SECTION <u>28</u> TOWNSHIP <u>28N</u> RANGE <u>7W</u> NMPM. |  | 10. Field and Pool, or Wildcat<br>Basin Dakota          |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>6083' GL  |  | 12. County<br>Rio Arriba                                |

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

|  |   |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            |


#### SUBSEQUENT REPORT OF:

|   |   |
|---|---|
| REMEDIAL WORK <input type="checkbox"/>                      | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/>         | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04-06-75 Spudded well. Drilled surface hole.

Ran 5 joints 9 5/8", 32.3#, J-55 surface casing, 193' set at 205'. Cemented with 224 cu. ft. cement. Circulated to surface. Waited on cement 12 hours; held 600#/30 minutes.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|                                    |                                  |                           |
|------------------------------------|----------------------------------|---------------------------|
| SIGNED <u>A. J. Lucas</u>          | TITLE <u>Drilling Clerk</u>      | DATE <u>April 7, 1975</u> |
| APPROVED BY <u>Ernest C. Lucas</u> | TITLE <u>SUPERVISOR DIST. #3</u> | DATE <u>APR 8 1975</u>    |
| CONDITIONS OF APPROVAL, IF ANY:    |                                  |                           |