5-USGS (Durango) 1-McHugh 1-File	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Contract 83
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas other dry hole	Jer 9. WELL NO.
2. NAME OF OPERATOR	1
Jerome P. McHugh 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Wildcat
Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space pelow.)	AREA Sec_18_T28N_R3W
AT SURFACE: 840' FSL - 1190' FEL	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Rio Arriba NM
AT TOTAL DEPTH:	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7220' GL 7232' RKB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly including estimated date of starting any proposed work. If well measured and true vertical depths for all markers and zones per This well was plugged and abandoned in the Spotted 36 sx cement plug (42.48 cu ft) 	following manner:
2. Shot off 4-1/2" csgg @ 1533'	OIL COM CO
3. Spotted 20 sx (23.6 cu ft) plug across	csg stub

Cement work complete 10-8-79. Set @ _ Subsurface Safety Valve: Manu. and Type ____ 18. I hereby certify that the foregoing is true and correct 11-27-79 Agent (This space for Federal or State office use)

Installed dry hole marker with 3 sx cement, filled pits and cleaned location.

_____ DATE _

Spotted 28 sx (33.04 cu ft) plug @ bottom of surface casing @ 200

__ TITLE _

4.