UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED								
Bu	dget Bur	eau No.	100	04-01	35			
	Expires:	March	31,	1993				

5. Lease Designation and Serial

			and the second second		
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

NM-14916 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6 If Indian, Allottee or Tribe Na Use "APPLICATION FOR PERMIT - " for such proposals. 7. If Unit or CA, Agreement Designation 1. Type of Well 8, Well Name and No. _ Well Valencia Canyon Unit 2. Name of Operator 9. API Well No. Gail M. Jefferson, RM 1942 Amoco Production Company 3003921594 3. Address and Telephone No. (303) 830-6157 10. Field and Pool, or Exploratory Area P.O. Box 800, Denver, Colorado 80201 Choza Mesa Pictured Cliffs 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec. 22 T 28N R 4W Unit D 1160'FNL 1140FWL New Mexico Rio Arriba CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Recompletion New Construction Notice of Intent Plugging Back Non-Routine Fracturing Water Shut-Off Subsequent Report Casing Repair Altering Casing Conversion to Injection Cleanout Well Bore inal Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 5/24/93 MIRUSU. NWDH, NUBOP. TIH w/ 3 jts tbg and tag fill. Tally OH w/tbg. Run csg insp log 300' to 4300'. TIH w/wireline CIBP, set at 4295' KB > TIH w/scraper to 4250'. TOH. TIH w/pkr, set at 3848'. Drop standing valve and test tbg to 3000#. Held for 15 min. Test csg above pkr to 500#, csg failed. Decision made to frac and then fix csg leak. Experienced frac problems with bender and screened out after 11,670 gas and 160 sx sand pumped (avg rate 7 ppg, max rate 10 ppg). TIH and CO SN & TOH w/pkr, TIH w/ BP & Pkr and isolated leak at 508-39'. run cbl and verified cmt across Ojo Alamo. Cmt ok. TIH and perf 2 spf at 565'. Circ water through perfs to surface. Dye test = 35 bbls. TIH w/pkr, set at 60'. Circ wtr through perfs and pumped 20 bbls cmt. Lost circ press = 1000#. Reversed out excess cmt and step squeezed w 1/2 bbl cmt up to 500#. After 15 min. press dropped to 150#. Repeat step squeeze w/ 1/2 bbl cmt up to 500#. Held for 15 min. SI well w/500#. TIH w/scraper & tagged cmt at 287'. Drilled out to 575' and press test csg. Held. TOH. TIH & retrieve RBP. TOH. Drilled out CIBP but BP stuck at 4432'. TIH w/ tbg & land at 4343' with seating nipple at 4312'. NDBOP, NUWH. 6/9/93 RDMOSU. RTP OIL COM, DAV 03-10-1995 Business Assistant (This space for Federal or State office use Title Approved by Conditions of approval, if any: MAR 1

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States

any false, ficticious, or fraudulent statements or