Meter Number:90279


Location Name: VALENCIA CANYON UNIT #35

Location:TN-28 RG-04 SC-34 UL-M

2 - Federal

NMOCD Zone:OUTSIDE

Hazard Ranking Score:00



### RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone  $10^{-9}$  to  $10^{-13}$  cm/sec Shale  $10^{-12}$  to  $10^{-16}$  cm/sec Clay  $10^{-12}$  to  $10^{-15}$  cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

FIELD PIT SITE ASSESSMENT FORM FIRED SERVICES

GENERAL	Meter: 9027 Location: VALENCIA CANYON VINT #35  Operator #: 0203 Operator Name: Arroco P/L District: BLOOMFIELD  Coordinates: Letter: M Section 34 Township: 28 Range: 4  Or Latitude Longitude  Pit Type: Dehydrator Location Drip: X Line Drip: Other:  Site Assessment Date: 5-15-94 Area: 10 Run: 62
SITE ASSESSMENT	NMOCD Zone:  (From NMOCD  Maps)  Inside  Outside  Outside  (2)  Maps)  Depth to Groundwater  Less Than 50 Feet (20 points)  Forest  Less Than 50 Feet (20 points)  Greater Than 100 Ft (0 points)  Wellhead Protection Area:  Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source?  (1) YES (20 points)  Horizontal Distance to Surface Water Body  Less Than 200 Ft (20 points)  Cycenter Than 1000 Ft (10 points)  Cycenter Than 1000 Ft (0 points)  Cycenter Than 1000 Ft (0 points)  Cycenter Than 1000 Ft (0 points)  Cycenter Than 1000 Ft (10 points)  Cy
REMARKS	Remarks: TWO PITS ON COCATION, ONE TO CLOSE

## FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 90279 Location: Valencia Canyon Unit #35  Coordinates: Letter: M. Section 34 Township: 28 Range: 4  Or Latitude Longitude  Date Started: 6-17-94 Area: 62 Run: 62
FIELD OBSERVATIONS	Sample Number(s): \( \frac{1}{2} \) Feet  Sample Depth: \( \frac{1}{2} \) Feet  Final PID Reading \( \frac{15}{2} \) PID Reading Depth \( \frac{1}{2} \) Feet  Groundwater Encountered \( \begin{align*} \begin{align*} \frac{1}{2} \end{align*} \) Approximate Depth \( \frac{1}{2} \) Feet
CIOSIIRE	Soil Disposition:  Envirotech (1) (3) Tierra  Other Facility (2) Name:  Pit Closure Date: 6-17-94 Pit Closed By: BET
Joyna March	Remarks: EPNG Line markers. U'soulstane  Signature of Specialist: Valle Willown  (SP3191) 04/07/5

# FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

### SAMPLE IDENTIFICATION

	Field ID	Lab ID	
SAMPLE NUMBER:	VW 217	9454-0	
MTR CODE   SITE NAME:	10274	N/A	
SAMPLE DATE   TIME (Hrs):	4-17-94	1225	
SAMPLED BY:	N/A		
DATE OF TPH EXT.   ANAL.:	6-20-94	6120194	
DATE OF BTEX EXT.   ANAL.:	NIY	N/A	
TYPE   DESCRIPTION:	VG	Today fine sand	
· ·			

REMARKS:

### RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
TANAMETE.			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG			-	
TPH (418.1)	1100 1110	JWJ 6/22/94 MG/KG			1.90	28
HEADSPACE PID	415	PPM				
PERCENT SOLIDS	90,4	%				


- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

The Surrogate Recovery was at	NA	_% for this sample	All QA/QC was acceptable.
Narrative:			
		· · · · · · · · · · · · · · · · · · ·	

DF = Dilution Factor Used

Pon

7/14/411



Initial mass of sample, g

Volume of sample after extraction, ml 39.000

Petroleum hydrocarbons, ppm 1109.238 Net absorbance of hytrocarbons (2930 cm-1) 0.134

