

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

Fee

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name San Juan 28-7 Unit
2. Name of Operator EL PASO NATURAL GAS COMPANY	8. Farm or Lease Name San Juan 28-7 Unit
3. Address of Operator Box 990, Farmington, New Mexico 87401	9. Well No. 249
4. Location of Well UNIT LETTER <u>H</u> , <u>1610</u> FEET FROM THE <u>North</u> LINE AND <u>830</u> FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>28-N</u> RANGE <u>7-W</u> N.M.P.M.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 5953 GL	12. County San Juan

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-9-78 Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 323# surface casing, 192' set at 206'. Cemented with 224 cu. ft. cement. Circulated to surface. Waited on cement 12 hours; held 600#/30 minutes.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Drilling Clerk DATE July 12, 1978

APPROVED original Signed by A. R. Kendrick

TITLE SUPERVISOR

DATE JUL 14 1978

CONDITIONS OF APPROVAL, IF ANY:

