4-14-14-1

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Э.	LEA	ASE
	SE	079250

DEFARIMENT OF THE INTERIOR	Sr_U/9.25U	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 28-5 Unit 8. FARM OF LEASE NAME	
1. oil gas 🗓 other	San Juan 28-5 Unit  9. WELL NO.	
2. NAME OF OPERATOR	102	
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Basin Dakota	
Box 289, Farmington, New Mexico \$7401	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> </ol>	AREA Sec. 11, T-28-N, R-5-WN.M.P.M.	
AT SURFACE: 1180'S, 470'E	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	Rio Arrica New Mexico	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		
FRACTURE TREAT  SHOOT OR ACIDIZE.		
REPAIR WELL	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING	change on Form 9-330.)	
MULTIPLE COMPLETE		
ABANDON*		
(other)		
including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent  -79: PBTD 3896'. Tested casing to 4000#, OK, Per 8835,3857,8863,8868' W/1 SPZ. Fraced w/ 67,1 Flushed w/ 5880 gal. wtr.	rfed 8758,8763,8768,8812,8825,8830	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.	
18. I hereby certify that the foregoing is true and correct		
SIGNED A. Suisco TITLE Drilling Cle	erk October 8, 1979	
(This space for Federal or State office	ce use)	
APPROVED BY TITLE	DATE	
CONDITIONS OF APPROVAL, IF ANY:	DCT 16 1979	
	# 1	

\*See Instructions on Reverse Side

S. GEOLOGICAL SURVEY