A CORDINSPECTOR

DEC 2 9 1997

Homoved

Meter Number:90796
ocation Name:SAN JUAN 28-5 #103
Location:TN-28 RG-05
SC-23 UL-H
2 - Federal
NMOCD Zone:OUTSIDE
Hazard Ranking Score:00

DECEIVED

APR 1 4 1997

ONL COM DAY

OIL GOM. DIV. Divi. 3

RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10^{-9} to 10^{-13} cm/sec Shale 10^{-12} to 10^{-16} cm/sec Clay 10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

EL MSO FIELD SERVICES


FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 90796 Location: SAN JUAN 28-5 # 103 Operator #: 2999 Operator Name: MERIDIAN P/L District: BloomFIELD Coordinates: Letter: # Section 23 Township: 28 Range: 5 Or Latitude Longitude Pit Type: Dehydrator X Location Drip: Line Drip: Other: Site Assessment Date: 5.27.99 Area: 10 Run: 61
	NMOCD Zone: (From NMOCD Maps) Inside Outside Outside Depth to Groundwater Less Than 50 Feet (20 points) 50 Ft to 99 Ft (10 points) Greater Than 100 Ft (0 points) Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of
SITE ASSESSMENT	fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? (1) YES (20 points) (2) NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (1) 200 Ft to 1000 Ft (10 points) (2) Greater Than 1000 Ft (0 points) (3) Name of Surface Water Body (5urface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only) (2) > 100' TOTAL HAZARD RANKING SCORE: POINTS
REMARKS	Remarks: Two PITS ON LOCATION, WILL CLOSE ONLY ONE, PIT IS DRY, LOCATION 15 UP ON A MESA. REDLINE AND TOPO CONFIRM LOCATION IS OUTSIDE VI.Z.
[<u>æ</u> _	PUSH IN (SP3190) 04/08/94

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 75° Footage from Wellhead 45′

b) Length : ______3' Depth : _____3'



Rem	arks :	
***	CIALD (•

TOOK PICTURES AT 1:53 P.M.

DUMP TRUCK - BOBTAIL

Completed By:

Signature

5.27.94

Date

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 90796 Location: SAN JULY 28-5 *103 Coordinates: Letter: # Section 23 Township: 28 Range: 5 Or Latitude Longitude Date Started: 6-29-54 Area: 10 Run: 61
FIELD OBSERVATIONS	Sample Number(s): MK 62 Sample Depth: /2 Feet Final PID Reading PID Reading Depth Feet Yes No Groundwater Encountered [(1) [(2) Approximate Depth Feet
CLOSURE	
REMARKS	Remarks: EPNG- 1.NCS Marked Soil Brown Stight Hydrocarhen odor Signature of Specialist: Margan Killian (SP3191) 04/07/9



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

	SAMPLE	IDENTIFICA	ATION				
	Fiel	d ID		Lab ID			
SAMPLE NUMBER:			945555				
MTR CODE SITE NAME:				N/A			
SAMPLE DATE TIME (Hrs):			1054				
SAMPLED BY:	N/A						
DATE OF TPH EXT. ANAL.:	<u> </u>	0/94	(d30)94)				
DATE OF BTEX EXT. ANAL.:	N (4		Dak brown fine soud follow			! !	
TYPE DESCRIPTION:							
REMARKS:					/		
		RESULTS					
PARAMETER	RESULT	UNITS		QUALIF	FIERS		
			DF	Q	M(g)	V(ml)	
BENZENE		MG/KG					
TOLUENE		MG/KG					
ETHYL BENZENE		MG/KG					
TOTAL XYLENES		MG/KG					
TOTAL BTEX		MG/KG					
TPH (418.1)	36.6	MG/KG			2.08	28	
HEADSPACE PID	25	PPM					
PERCENT SOLIDS	P9.2	%					
he Surrogate Recovery was at arrative:	- TPH is by EPA Method 4	18.1 and BTEX is by EPA % for this samp		was accep	table.		
F = Dilution Factor Used	D			7/14/4	·//		