Contract of the second

5. LEASE

## UNITED STATES

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE NM 02805 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331—C for such proposals.)  1. oil gas well other  2. NAME OF OPERATOR  E1 Paso Natural Gas Company  3. ADDRESS OF OPERATOR	7. UNIT AGREEMENT NAME San Juan 28-6 Unit  8. FARM OR LEASE NAME San Juan 28-6 Unit  9. WELL NO. 5A  10. FIELD OR WILDCAT NAME Blanco M.V.
P.O. Box 289, Farmington, New Mexico 87401  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  AT SURFACE: 1700'S, 1690'E  AT TOP PROD. INTERVAL:  AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-28-N, R-6-W  N.M.P.M.  12. COUNTY OR PARISH Rio Arriba New Mexico  14. API NO.
REPORT, OR OTHER DATA  REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6410' GL
FRACTURE TREAT	(NOTE: Report results of multiple completion or zone change on Form 9–330.).
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinents.  5-31-79: Spudded well. Drilled surface hole. surface casing, 209' set at 223'. Concentrated to surface. WOC 12 hours.	Ran 5 jts. 9.5/8", 36#, K-55 emented w/224 cu. ft. cement. held 600#/30 minutes. held 600#/30 minutes. held 600#/30 minutes.
Subsurface Safety Valve: Manu. and Type  18. I hereby certify that the foregoing is true and correct  SIGNED  TITLE Drilling Cle:	rk DATE June 4, 1979
TITLE STEED TITLE STEED TITLE STEED THE STEED	

\*See Instructions on Reverse Side