UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	5. LEASE SF 079192 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME San Juan 28-6 Unit 8. FARM OR LEASE NAME San Juan 28-6 Unit 9. WELL NO. 47A 10. FIELD OR WILDCAT NAME Blanco M.V. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T-28-N, R-6-W N.M.P.M.
AT SURFACE: 890'N, 790'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6702 GL (NOTE: Report results of multiple completion or zone 1070
PULL OR ALTER CASING	change on Form 9-330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen 4-30-79: Spudded well. Drilled surface hole.	irectionally drilled, give subsurface locations and t to this work.)*
5-01-79: Ran 5 jts. 9 5/8", 36#, H-40 surface Cemented w/224 cu. ft. cement. Circ 12 hours; held 600#/30 minutes.	e casing, 205' set at 218'. culated to surface. WOC
Subsurface Safety Valve: Manu. and Type	Set @ # # # # # # # # # # # # # # # # # #
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Drilling Cle	rk DATE May-1, 1979
(This space for Federal or State office use)	
APPROVED BYTITLECONDITIONS OF APPROVAL, IF ANY:	DATE DATE