

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
El Paso Natural Gas Company
3. ADDRESS OF OPERATOR
Box 289, Farmington, New Mexico 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1940'S, 1690'E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

- ☒
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-14-79: TD 3564'. Ran 93 Jts. 7", 20.0#, K-55 intermediate casing, 3552, set at 3564'. Cemented w/264 cu. ft. cement. WOC 12 hours, held 1200#/30 min. Top of cement 2200'

7-17-79: TD 5924'. Ran 77 jts. 4 1/2", 10.5#, KS casing liner, 2516' set at 3408-5924'. Float collar set at 5907'. Cemented w/438 cu. ft. cement. WOC 18 hours.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED A. D. Bises TITLE Drilling Clerk DATE July 18, 1979

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

5. LEASE SF 078417	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME San Juan 28-7 Unit	
8. FARM OR LEASE NAME San Juan 28-7 Unit	
9. WELL NO. 22 A	
10. FIELD OR WILDCAT NAME Blanco MV	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-28-N, R-7-W N.M.P.M.	
12. COUNTY OR PARISH Rio Arriba	13. STATE New Mexico
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 6638' G.L.	

RECEIVED

JUL 23 1979

State

WILSON SERVICE COMPANY

FORM 432-2

TEMPERATURE SURVEY

COMPANY.....El Paso Natural Gas Co.
WELL.....22A.....LEASE.....San Juan 28-7
COUNTY.....Rio Arriba.....STATE.....New Mexico
SEC.....TWP.....RGE.....
APPROX. TOP CEMENT.....2200'
Survey Begins at.....1500'.....Ft. Ends at.....350'.....Ft.
Approx. Fill-Up.....Max. Temp.....
Log Measured From.....KB.....Run No.....
Casing Size.....Casing Depth.....Diam of Hole.....Depth.....
7".....from.....to.....8 3/4".....from.....to.....
from.....to.....from.....to.....
Date of Cementing.....7/14/79.....Time.....4:00 AM
Date of Survey.....7/14/79.....Time.....12:00 Noon
Amount of Cement.....90 Scks 65/35 Class B Poz 6% Gel 2% CACL + 100
Scks Class B 2% CACL.
Recorded by.....Griffey.....Witnessed by.....

REMARKS OR OTHER DATA

: to Alamo 2380'.

TEMPERATURE IN DEGREES FAHRENHEIT

