SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

Form Approved. Budget Bureau No 42-R1424

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF079729 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME	
1. oil gas well other	Valdez 9. WELL NO.	
2. NAME OF OPERATOR E1 Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1640'N, 1440'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	2 10. FIELD OR WILDCAT NAME— Choza Mesa P.C. Ext. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 16, T-28-N, R-4-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 7429' GL	
FRACTURE TREAT		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-16-79: PBTD 4549'. Tested casing to 4000#, OK. Perfed 4266,4276,4286,4297,4309, 4362,4373,4381,4390,4399,4408,4423,4433,4443,4453,4462'. W/1 SPZ. Fraced w/150,402# 10/20 sand, 155,402 gal. wtr. Did not flush.

Subsurface Safety Valve: Manu. and Type)		Set @ Ft.
13. 11. 100, certify and the foreschapite signed	TITLE Drilling Clerk	DATE	October 17, 1979
	(This space for Federal or State office us	e)	
APPROVED BY	TITLE	DATE _	