5. LEASE

harmen !

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	SF 078417 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 28-7 Unit 8. FARM OR LEASE NAME
1. oil gas X other	San Juan 28-7 Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401	8A (PM) 10. FIELD OR WILDCAT NAME Blanco PC Ext. & Blanco MV 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1740'S, 1120'E AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 18, T-28-N, R-7-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6878 GL
TEST WATER SHUT-OFF X FRACTURE TREAT	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent 4-29-80: TD 3807'. Ran 89 joints 7", 20#, K-55 inter Cemented w/ 317 Cu. ft. cement. WOC 12 hour cement 3200 '.	rectionally drilled, give subsurface locations and to this work.)* mediate casing3796' set at 3807'
5-1-80: TD 6209'. Ran 62 joints 4 1/2", 10.5#, KS of Float collar set at 6192'. Cemented w/ 438	
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED. Drilling Cler	Set @ Ft. ** May 16, 1980
(This space for Federal or State off	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE ACCEPTED FOR RECORD

MAY 22 1980

*See Instructions on Reverse Side