UNITED STATES DEPARTMENT OF THE INTERIOR

	•	
5. LEASE SF 078417		/
6. IF INDIAN, ALLOTT	EE OR TRIBE	NAME /

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME San Juan 28-7 Unit	
1. Oil gas Other	8. FARM OR LEASE NAME San Juan 28-7 Unit	
2. NAME OF OPERATOR El Paso Natural Gas Company	9. WELL NO. 239E	
3. ADDRESS OF OPERATOR P.O. Box 289, Famington, NM 87401	10. FIELD OR WILDCAT NAME Basin Dakota	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-28-N, R-7- NMPM	
AT SURFACE: 1030'N, 930'W AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico	
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6645' GL	
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	lirectionally drilled, give subsurface locations and	
81: PBTD 7759'. Tested casing to 4000# 7553,7562,7571,7580,7647 7679,7685, Fraced w/ 187,000# 20/40 sand, 144,	7710,7719,7728,7737' W/1 SPZ.	

4-21-

gal. wtr.

OIL CON. COM. DIST. 3

	1		
12	I hereby certify that the	e foregoing is true	and correct

Subsurface Safety Valve: Manu. and Type _

TITLE Drilling ClerkATE April 22, 1981

(This space for Federal or State office use)

ACUEPANG FOR RECORD

APR 3 0 1981

*See Instructions on Reverse Side

_ DATE ___

