9-6-80:

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

	Dudget Duleau No. 42-111424
ı	5. LEASE
	SF 078417
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
-	
	7. UNIT AGREEMENT NAME
t	San Juan 28-7 Unit
_	8. FARM OR LEASE NAME
	San Juan28-7 Unit
	9. WELL NO.
	231 E
_	10. FIELD OR WILDCAT NAME
	Basin Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OR
_	AREA Sec. 16, T-28-N, R-7-W
	NMPM

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	San Juan 28-7 Unit 8. FARM OR LEASE NAME			
1. oil gas X other	San Juan28-7 Unit			
	9. WELL NO.			
2. NAME OF OPERATOR	231 E			
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR	Basin Dakota			
P.O. Box 289, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR			
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> </ol>	NMPM			
AT SURFACE: 1915'S, 1930'W	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico			
	14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6228' GL			
TEST WATER SHUT-OFF				
FRACTURE TREAT				
SHOOT OR ACIDIZE				
REPAIR WELL	(NOTE: Report results of multiple completion or zone			
PULL OR ALTER CASING	change on Form 9-330.)			
MULTIPLE COMPLETE				
ABANDON*	•			
(other)				
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertined.	directionally drilled, give subsurface locations and ent to this work.)*			
Spudded well. Drilled surface hole. Ran 5 surface casing 230' set at 244'. Cemented w.				
Circ. to surface. WOC 12 hours; held 600#/30	minutes.			
Company of the Compan				
RECEIVED	or and the second of the second			
A Show to Love I be I have been				
SEP 65 1880	SFFIRE			
Our College	100			
2	OIL CON. CI			
U, S. GTOLOGICAL SURVEY FARMINGTON, N. M.	DIST 3			
LAMPINGTON, IS. III.				

				-	<u></u>
Subsurface Safety Valve: Manu. and Type				Set @	Ft.
18. I hereby certify that the fore	going is true and correct  Adultation Drilling Clerk	_ DATE _	Setp.	8, 1980	
	(This space for Federal or State office us	2)			<del></del>
APPROVED BY	TITLE	DATE	<u> </u>	· · · · · · · · · · · · · · · · · · ·	<del></del>

SEP 1 1 1980

\*See Instructions on Reverse Side