Form 9-331 Dec. 1973

APPROVED BY _

CONDITIONS OF APPROVAL, IF ANY:

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078497A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR E1 Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 4289, Farmington, New Mexico 87499	7. UNIT AGREEMENT NAME San Juan 28-7 Unit 8. FARM OR LEASE NAME San Juan 28-7 Unit 9. WELL NO. 266 10. FIELD OR WILDCAT NAME S. Blanco P. C. Ext. 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1025'S, 1070'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 9, T-28-N, R-7-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6692' GL
MULTIPLE COMPLETE	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 12-20-83 Tested casing to 4000# O. K. P.B.T.D. 3395, 3401, 3416, 3422, 3428, 3432' w 10/20 sand and 44,300 gallons treated of 1 ball each. Flushed w/850 gallon	directionally drilled, give subsurface locations and not to this work.)* 1. 3479'. Perforated 3389, 1/1 SPZ. Fractured w/38,000# 1. water. Dropped 14 sets is water. 1. JAN 101984
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby certify that the foregoing is true and correct SIGNED	erk January 4, 1984
(This space for Federal or State office use)	

TITLE DATE THE TAKE TO BE A SHOWN THE ASSET

RY SMM