## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	cices and Reports on Wells		
		5.	
1. Type of Well GAS		6.	NM-03583 If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator			
BURLINGTON RESOURCES OIL	& GAS COMPANY	8.	San Juan 28-5 Unit Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700			San Juan 28-5 U #41 API Well No.
4. Location of Well, Footage, S	Sec., T, R, M	10.	30-039-25626 Field and Pool
950'FNL, 1070'FWL, Sec.32, 1		11.	Blanco MV/Basin DK County and State Rio Arriba Co, NM
_X_ Subsequent Report Final Abandonment  13. Describe Proposed or Comp	Plugging Back No Casing Repair Was Altering Casing Co	ew Construction-Routine inter Shut of the conversion to	Fracturing ff
-	3400'. TOOH. TIH w/chemical	cutter. Ch	emical cut 4 1/2" csç
4-2-97 TOOH w/4 1/2" csg	g. TIH w/swedge. Work swedge w/retrieving tool. Latch RBF		
	# w		
		2	
14. Thereby sertify that the foregoing is true and correct.		ect.	<u> </u>
signed Signy Statuted	Title Regulatory Adminis	strator_Date	
(This space for Federal or Stat		Da ACCI	EPTED FOR REGORD
APPROVED BY	Title	_ Dave	APR 15 1997

FARMINGTON DISTRICT UFFICE