

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires: November 30, 2000

5. Lease Serial No.
SF-078500-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

8. Well Name and No.
SAN JUAN 28-7 UNIT 249M

9. API Well No.
30-039-25802

10. Field and Pool, or Exploratory
BLANCO MV/BASIN DK

11. County or Parish, and State
RIO ARRIBA COUNTY, NM

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
CONOCO INC. Contact: SHELLY COCHERELL
E-Mail: scocherell@trigon-sheehan.com

3a. Address
126 ROCK POINT DRIVE, STE. B
DURANGO, CO 81301
3b. Phone No. (include area code)
Ph: 970.385.9100 Ext: 136
Fx: 970.385.9107


4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 30 T28N R7W Mer SWSE 855FSL 2365FEL

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PLEASE REFER TO ATTACHED DETAIL INFORMATION PERTAINING TO CLEANOUT OF THIS WELL



14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #6482 verified by the BLM Well Information System
For CONOCO INC., sent to the Farmington
Committed to AFMSS for processing by Lucy Bee on 08/20/2001 ()**

Name (Printed/Typed) SHELLY COCHERELL

Title AGENT

Signature

Date 08/16/2001

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ****

NMOCD

SAN JUAN 28-07 UNIT #249M

3003925802

855' FSL – 2365' FEL, SECTION 30, T28N-R07W
RIO ARriba COUNTY, NM

Date	Operations
6/14/2001	MIRU Key Energy 34. TIH with 102' of tubing and tagged bottom. Strapped out of hole with tubing. Tagged @ 6893', 13' below the bottom perf. No perfs are covered. Only scattered very light scale on tubing. No evidence of a brige on the backside. Plunger was stuck in bottom of bottom joint of tubing. SWION.
6/15/2001	SICP: 150 PSI, bled well down. TIH with 75 joints 2 3/8" tubing. LD same 75 joints 2 3/8" tubing. Prep to run 75 joints 2 3/8" fl4s tubing for bottom tubing in well. SWION.
6/18/2001	SICP: 280 psi. Bled well down. PU ms, SN, 14' sub, 80 joints 2 3/8" 4.0# j55 ab fl4s, xo, 140 joints 4.7# J55 8rd eue tubing. Landed tubing @ 6802'. ND BOP. NU tree. RD blooey line. RDPU. Cleaned location. Moved rig out.

NOV 3 7 2001

