

DEVIATION REPORT

Name of Company

Burlington Resources Oil & Gas Company

Lease Name and Number

SAN JUAN 28-5 UNIT #92M

Pool and Formation

Blanco Mesaverde/Basin Dakota

Address

P. O. Box 4289, Farmington, NM 87499

Unit Letter

1,335 FNL -465 FWL E

Sec.

24

Twn.

028N

Rge.

005W

County

RIO ARRIBA

Depth (Ft.)**Deviation (Degrees)**


0	.00
247	.75
744	.75
1,235	.75
1,734	2.00
2,267	3.00
2,516	2.50
2,766	2.00
3,265	3.00
3,512	2.50
3,916	2.75
4,320	1.50
4,663	1.00
8,795	.75

RECEIVED
SEP - 1 1999
OIL CON. DIV.
DIST. 3

Air Hammer Used? YES/ NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for BURLINGTON RESOURCES OIL AND GAS CO., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 27th day of August, 1999



Notary Public in and for San Juan County, New Mexico

My commission expires August 17, 2000