



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 077520-A
Unit San Juan 20-5 Unit
14-08-001-949

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

....., 19 57

Well No. 26 is located 1500 ft. from [N] line and 1500 ft. from [E] line of sec. 26

NE Sec. 26 26N 5W N.M.P.M.
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Blanco M.V. Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7236 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 4-20-57. Total Depth 6536'.
Run 54 joints 5 1/2", J-55, 15.50#, casing (2000') set from 4295' to 6534'.
with 145 sacks regular cement, 145 sacks Pozmix, 1 1/2# Sulphur/seck, 6#
Gel, followed with 50 sacks regular cement.
Held 1000# for 30 minutes.
Top of cement by temperature survey at 4275'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 971
Farmington, New Mexico

By Original Signed C. D. COX

Title Petroleum Engineer