REGEIVEM

Form 9-331 Dec. 1973		~	° [//]		n Approved. get Buresu No. 42–R1424				
Dec. 1973	UNITI	ED STATES	FEB27	71900 1	LEASE	7 A ()	.	· 5	
	DEDADTMENT	OF THE INTE	HIME	1504	SF 0802387		<u> </u>	14 <u>5</u>	
	OF ANTIMENT	ED STATES OF THE INFE	NOGON	. Dut	6. IF INDIAN, A		TRIBE NA	MF	
	GEULUG	ICAL SURVE	DIST	2/1/	.	25 = 13		₹ 3.5	
		NO DEDODE		4	7. UNIT AGRE	EMENT NAME	<u>_</u>	<u> </u>	
	Y NOTICES A				7. ONLI AGILL	= 2 = .	· ==	2006 1006 1006	
(Do not use this reservoir. Use Fo	form for proposals to	idrill or to deepen or proposals.)	plug back to	different	8. FARM OR LI			<u> </u>	
		•			Morgan			1 2	
1. oil	gas 🗆	ther		- 1	 	- 1151	- 	-	
well —					9. WELL NO.	12 7 7	1-8	1.5	
2. NAME OF		. •		4	1	3.5 - 5		E -	
Merrion	Oil & Gas Co	rporation			10. FIELD OR W		E 3		
	OF OPERATOR				Gallegos G		<u> </u>		
P. O. Bo	x 1017, Farm	ington, New	Mexico 8	37499	11. SEC., T., R.,		2	_	
4. LOCATION	OF WELL (REPO	RT LOCATION CLE	EARLY. See s	pace 17	AREA	155 × 3	3 48	<u> </u>	
below.)	5001 7	7 5001			Sec. 31, 1				
AT SURF	ACE: 500 F. PROD. INTERVAL:	SL and 500'	F.ET		12. COUNTY OF		-	_	
AT TOTAL	DERTH.	Same			Rio Arriba	Ne			
	Ja		171105 05		14. API NO.		를 걸릴	15 T	
	PPROPRIATE BOX		ATURE OF	NOTICE,		TERO.		=	
REPURI,	OR OTHER DATA				15. ELEVATION 5833' GL	S (SHOW_DF	, KDB, AI	ND WD)	
REQUEST FOR	R APPROVAL TO:	SUBSEOUE	NT REPORT	OF:	2623 (31)	<u>- 3558 -</u>	<u> </u>	.	
TEST WATER	_]			0 1 2 2		÷	
FRACTURE TE			j			5 5 5	그 글	<u> </u>	
SHOOT OR A	=	. 🗀				ପୁରୁ ପୂର୍ବ ଜୁନ୍ଦୁ କୁ	10 E	# F	
REPAIR WELL	. 🔲]		(NOTE: Report re			n of zone	
PULL OR ALT	=	<u>_</u>	1			on Form 9-330)	<u> </u>		걸
MULTIPLE CO	=	<u> </u>		EC		20 E	- T	<u>چ</u> چ	ofter the state
CHANGE ZON ABANDON*		<u> </u>	1		29 20 20 20 20 20 20 20 20 20 20 20 20 20	iorla ineti ineti bite	SE 0.2	96.00 Offices	દુ
(other)	LX.	L	1	FEB		8 C C 2		===	-
`					<u> </u>	29 # 3	ट ए-		-
17. DESCRIB	E PROPOSED OR estimated date of	COMPLETED OPER	RATIONS (C	early state	all pertinent de	tails, and give	e pertinen	it dates,	
including	estimated date of and true vertical (starting any prope depths for all mark	ers and zone	r well is al es pertinen	t to this work.)*	, give spicauri	ace iocati	Oris and	
				•	·		- 복 5 출	F	
	to plug and	plug across	Callum	norfa 1	906 - 40301	Sand Server	abov	ලියි. තුරී	
1.	Spot 12 sx	plug across plug to cov	Garrup ;	herra 4	690 - 4939 cc top of c	and July	z z z z	- <u>.</u>	
	Spot 12 sx Perforate						de and	e 4 Cont	
٥.		op of Mesave		030 .	riace 2/ SX	Brita vities	in and		
4	Place 12 s	op or mesave	rue. « EO f+	holow	curface nine	. na anoul f			1501
4.									130 +
-		x down annul					- Luge - 2 3	22 <u>- 1</u>	
_	Place 10 s	_	_						
6.		rface per BL				o a ∓ { } duction_ca	in a mari	4500	Tioner .
rop of	cement - sur	Lace Casing ESTIMAT	ED FORMA	rich fö	PS Proc		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4000	, remb.
Ojo Ala	omo	Surface		Pictur	ed Cliffs		Manco	s	3870
Kirtlan	nd	Behind surfa	ce pipe	Lewis		7,1400	≟ Çalalı	p ်	4708

Cliffhouse Fruitland Subsurface Safety Valve: Manu. and Type

18.	I hereby	Sertify 1	that the	foregoi	ing is	s true	and	correct
	1	/		<i>/</i>				

Operations Managerate (This space for Federal or State office use)

_ TITLE .