

■			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office NM
Lease No. 03413
Unit L-604

RECEIVED

JAN 31 1954

U. S. GEOLOGICAL SURVEY
FELLS

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 30 19 58

Well No. 1 is located 660 ft. from N line and 1900 ft. from W line of sec. 33

SE SW/4 Sec. 33 27-N 12-W NMPM
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wilcox San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 5961 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1-16-58. Total Depth 5202'.

Ran 56 joints 5-1/2", 15.50#, J-55 Casing (1220') set at 3981'-5201' with 100 sacks regular cement, 100 sacks Pozmix, 2% Gel.
Held 1000# for 30 minutes.
Top of cement by temperature survey at 3981'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Products Company
Address Post Office Box 1546
Farmington, New Mexico

ORIGINAL SIGNED BY: JOSEPH E. KRE
By _____
Title Petroleum Engineer

ORIGINAL SIGNED BY: JOSEPH E. KREGER

By _____
Title **Petroleum Engineer**