UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR	Sr U8U238A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CHAIDDY MOTICES AND DEDTER ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	美麗麗 金 3 0000
(Do not use this form for proposals to drill or to depend or to place to proposals of the p	8. FARM OR LEASE NAME
	Morgan The Grand State of Stat
1. oil gas other AUG 16 1984 2. NAME OF OPERATOR	
wen wen wen other	9. WELL NO. 3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
2. NAME OF OPERATOR Merrion Oil & Gas Corporation	
	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Gallegos Gallup
P. O. Box 1017, Farmington, New Mexico 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA GOOD OF THE PROPERTY OF T
below.)	Sec. 31, T27N F R12W
AT SURFACE: 2310' FNL and 330' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH:	San Juan - New Mexico
Same	_ 14. API NO 글플램을 된 신원활경 ::
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<u> </u>
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW_DF, KDB, AND WD)
	5894 GL 3
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5 L 1 2 L 2 L 2 L 2 L 2 L 2 L 2 L 2 L 2 L
TEST WATER SHUT-OFF	6 8 8 8 8 7 7 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
FRACTURE TREAT	
SHOOT OR ACIDIZE	AND
REPAIR WELL PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	change on Tolling—330.)
CHANGE ZONES	그런 티가석의 그는 그 폭폭혈급 그 보는 중요했습니다.
ABANDON* X Section	
(omer)	
	<u> </u>
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d 	te all pertinent details, and give pertinent dates
measured and true vertical depths for all markers and zones pertiner	nt to this work.)*
	ကြောင်းကြောင့် မြောင်းမြောင်းကြောင့် မြောင်းကြောင့် ကြောင့်ရှိသည်။ မြောင်းကြောင့် မြောင်းကြောင့်
Spot 35 sx (42.7 cu. ft.) across Gallup to 473	O' Squeezed perfs.
Shot hole @ 2075'. Placed 100' plug, 26 sx (3)	
casing.	1.72 Gu. 10.7, Instac and Odestac
	i de
Placed 12 sx (14.64 cu. ft.) plug across shoe.	
Tied onto Bradenhead and pumped 25 sx (30.5 cu	. it.) plug down casing amulus i
isolate shoe.	
Placed 10 sx (12.2 cu. ft.) surface plug.	
Erect dry hole marker. Completed 3/29/84.	
Reseeded and completed rehabilitation requirement	ents 7/25/84.
	en de la companya de La companya de la co
Substitute on Codety Values Manus and Tune	Set @FI
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	
ST I I	0 (0 (0.4
SIGNED / TITLE Operations M	anagerate 8/8/84

(This space for Federal or State office use)

*See Instructions on Reverse Side

AUG 15 1060
FARMINGTON KASOURCE AREA
SY.....