


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 03803
Unit Harmond #3



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

3-13, 19 52

Well No. 3 is located 1650 ft. from N line and 1650 ft. from E line of sec. 35

SW 1/4 sec. 35 27N 3N N. 27.5 W.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco-Largo San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6113 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 2-27-52

On 2-27-52 set 100' 10 3/4" new spiral guide welded joints circulated with cement.

Cement set 36 hrs. Drilled cement out of pipe.

Tested with 400# pump pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Great Lakes Oil-Chem. Co.

Address 502 Mich. Nat. Bk. Bldg.

Grand Rapids 2 Mich.

By E. J. Hampton
Title supt.

